



Verify that the wires have not broken off the PCB or broken or been pinched in the elbow.